



F:\2022\21976 ERI-SR60 Flood Study\789101\400-Engineering\Roadway\Sheets\Presentation DGNs\2 - Home Constructed after 1974.dgn 12/1/2023 11:01:09 AM smorr



**LEGEND**

-  - HOUSES BUILT AFTER DITCH MAINTENANCE IMPLEMENTATION
-  - TRINTER DITCH MAINTENANCE BOUNDARY LINE
-  - DRAINAGE AREA

**REL** RICHLAND ENGINEERING LTD  
A WALLACE PANCHER GROUP COMPANY

**2 - HOUSES CONSTRUCTED AFTER 1974 TRINTER DITCH MAINTENANCE PLAN IMPLEMENTATION**